


DEPARTMENT OF ENVIRONMENTAL RESOURCES

REVIEW NOTICE

This report, prepared by outside consultants, has been reviewed by the Department of Environmental Resources and approved for publication. The contents indicate the conditions that are existing as determined by the consultant, and the consultant's recommendations for correction of the problems. The foregoing does not signify that the contents necessarily reflect the policies, views, or approval of the Department.

CHALFANT RUN

MINE DRAINAGE STUDY




COMMONWEALTH OF PENNSYLVANIA
MILTON J. SHAPP - GOVERNOR
DEPARTMENT OF ENVIRONMENTAL RESOURCES
MAURICE K. GODDARD - SECRETARY

1975

ALEX HUTCHINSON & SON
REGISTERED ENGINEERS
508 REBECCA AVENUE
PITTSBURGH, PENNA. 15221

PENNSYLVANIA

SCALE IN MILES
10 5 0 10 20 30 40



STUDY AREA CHALFANT RUN

PLATE (A)

TABLE OF CONTENTS

	<u>Pages</u>
INTRODUCTION & WATERSHED DESCRIPTION	IW-1 through IW-7
SAMPLING PROGRAM & SOURCES OF POLLUTION	SP-1 thru SP-28
Water Flow Chart - Page SP 10	
ANALYSIS OF CONDITIONS	AC-1 thru AC-14
Plate B - page AC-4	
Plate C - page AC-5	
Plate E - page AC-6	
Plate D - page AC-11	
ABATEMENT RECOMMENDATIONS	AR-1 thru AR-5
Plate 400 -	page AR-4
CONCLUSION	C-1 and C-2
APPENDIX -- (A) SAMPLE & STREAM FLOW TEST RESULTS	
(B) REFERENCES	
(C) - Plate 500 Key Study Map	
(D) - Plate 501 - Gas & Oil Wells Map (Active & Abandoned)	